







Coppins Crossing—Molonglo River



Participant Comments

- Occasional slight rainfall recorded within 24 hrs of monitoring had no impact on results.
- Relationship between lower flows and temperature and a slight increase in algae and low dissolved oxygen.
- No river erosion however hill slopes are bare in forestry area;
- No noticeable sedimentation.
- Road bridge used for dumping of various items including cars parts and rubbish.
- Some Casuarina trees badly burnt and died while others are recovering.
- Willows burnt but survived fire.
- Weed species are flourishing.

Water Quality



Habitat Recovery



February 2003



March 2003



November 2003



January 2004