

2500	Other	City	14	65	31 Constitution Avenue Canberra 2601	National Convention Centre	Building identified on a second list of an additional 235 properties provided by ACT Property Group, after the cladding team questioned the completeness of	61.2	3	26.52	1	Low	EPDIO inspected by [redacted] on 06/04/19. Building identified on a second list of an additional 235 properties provided by ACT Property Group, after the cladding team questioned the completeness of the original list.	9b	A	4	ACP unclear	Unclear	Front and rear entrances	unknown			
								60	3	39.6	1	Low	Inspected by [redacted] on 13/11/2019. Even though the likely cladding is a small amount of signage information was applied to the risk tool and a moderate risk rating was achieved. Building identified on a second list of an additional 235 properties provided by ACT Property Group, after the cladding team questioned the completeness of the original list.	9b, 5 and 6	A		3	Yes Likely	Unknown				
								32	1	42.24	2	Low	Inspected by [redacted] on 13/11/2019. Information applied to the risk tool and a low risk rating was achieved. Building identified on a second list of an additional 235 properties provided by ACT Property Group, after the cladding team questioned the completeness of the original list.	9b	C		1	Yes Likely	Unknown				
								44	2	29.04	1	Low	Inspected by [redacted] on 15/11/2019. Information applied to the risk tool and a low risk rating was achieved. Building identified on a second list of an additional 235 properties provided by ACT Property Group, after the cladding team questioned the completeness of the original list.	9b	C		1	Yes Likely	Unknown				
								44	2	44	2	Low	Inspected by [redacted] on 18/11/2019. Information applied to the risk tool and a low risk rating was achieved. Building identified on a second list of an additional 235 properties provided by ACT Property Group, after the cladding team questioned the completeness of the original list.		S, C		1	Yes Likely	Unknown				
								68	3	39.6	1	Low	Inspected by [redacted] on 10/12/2019. Information applied to the risk tool and a low risk rating was achieved.	9b	C		1	Yes Likely	Unknown				
								88.4	4	17.136	1	Moderate	Inspected by [redacted] on 4/3/20. Information was applied to the risk tool and found to be moderate risk. Site assessment completed and tool indicates moderate risk, fire brigade inspection required.	9b	A or B				Unknown				
								44	2	47.52	2	Low	Inspected by [redacted] on 16/3/20. Information was applied to the risk tool and found to be low risk. Site assessment completed and tool indicates low risk, fire brigade inspection required.	2 and 7a	A		4	Yes Likely	Unknown				
								56	2	31.68	1	Low	Inspected by [redacted] on 16/3/20. Information was applied to the risk tool and found to be low risk. Site assessment completed and tool indicates low risk, fire brigade inspection required.	9b	B		2	Yes Likely	Unknown				